



PC-50

Capacity / Accuracy	3 kg - 0,1 g / 6 kg - 0,2 g / 15 kg - 0,5 g / 30 kg - 1 g.
Display	3 LCD back-light displays. 6 Digits 20 mm height.
Functions	Piece counting, preset tares, pieces checking alarm, accumulation.
Supply	Mains and internal rechargeable battery.
Pan	Stainless steel.
Dimensions	

